

21 December 2023

Port Works Notice: Jettie 4, 5 & 6 Demolition Notification

Project Scope


- Full deconstruction of jetties 4 & 5 and partial demolition of jetty 6.
- All identified broken piles and pile stumps will be cut at sea-bed level.
- Creation of a marked demarcation zone once the deconstruction is complete.
- Expected completion date is June 2024.

Project Status

- Demolition of Jetty 5 is completed. Demolition of Jetty 4 is ongoing.
- All broken piles were cut at the seabed level.

Current Hazards

- The chartlet below highlights the demolition zone and should be regarded as a 'no-go' zone for all vessels that are not under Pilotage control, but excluding LPC Harbour Tugs engaged in a ship movements. This is an area of reduced depth and potential submerged timber piles.
- Smith Crane Tug and Barge movements vessels are routinely moving from the work area to the oil berth vicinity to unload timber.
- Broken/submerged piles all identified broken piles have been cut at the sea-bed level.



Post Demolition Marking

- Following completion of the demolition work, hazardous areas will be marked as follows.
 - Steel piles at 20m spacing will be installed at the eastern wharf edge location of Jetty 4. These will be lit.
 - Marker buoys will be placed along the line running from the western outer end of Jetty 6 and the eastern outer end of Jetty 4. These will be lit.

Notice to Mariners (NTM)

A NTM was issued relating to this project work as follows:

NZ 61(P)/23 NEW ZEALAND - South Island - East Coast - Port of Lyttleton. Demolition works

- 1. Until further notice, demolition work to remove No.4, No.5 and No.6 jetties is underway.
- 2. An exclusion zone has been established bounded by the following positions:
 - a. 43°36'.281S., 172°43'.198E. (shoreline)
 b. 43°36'.380S., 172°43'.090E.
 c. 43°36'.290S., 172°43'.010E.
 d. 43°36'.248S., 172°43'.035E. (shoreline)
- 3. No vessel is permitted to enter the exclusion zone without consent, and mariners are requested to keep clear of the area, and exercise caution when accessing adjacent jetties.
- 4. All vessels will maintain a listening watch on Lyttelton Harbour Radio VHF channel 12.
- 5. Charting action will take place in due course.

Chart affected: NZ 6321

Southern Hydrographic Ltd. HITS 6321/304

Please contact Andrew Van der Bent, LPC Head of Marine Operations with any questions. 021-343095, andrew.vanderbent@lpc.co.nz